


# High dust load inlet filtration

## Stainless Steel Filter housing with acrylic end plate



### Problem – blocked filters shutting vacuum conveying process

Acrylic end plate enables the filter to be checked easily during process.



**mbar**

EST. 2001—NATIONWIDE

**VACUUM PUMP & BLOWER  
OVERHAUL SPECIALISTS**

**ANY WHERE  
ANY TIME  
ANY BRAND**



**[www.mbar.co.nz](http://www.mbar.co.nz)**

**24 hr phone 07 871 8192**