



No more filing or losing reports



Innovative web database

2500 pieces of equipment on line

Problem	Solution
Site engineers having to file off a large number of reports in a short time space	No Filing for site engineers
Site engineers having to find reports at breakdowns during the year	Access on line service records using, serial number, drive number or order number search 24/7
Insufficient information from customer given at the breakdown report	Access to pump records detailing pump type, model, serial #, port size, motor kW, photo, site map 24/7
Effective reporting for auditors	Recording of use of food grade oil
Communication with specialist companies when problem occur	Site engineer & specialist can communicate off the same page
Multiple pump failures in same location	Service stacked against pump location high lighting multiple failure, indicating potential process problem
Same pump failure in multiple locations	Service stacked against pump serial number highlighting multiple failures, indicating pump problem
Accessing information by field engineers when out of office	Data base available by remote access
Forward work planning	Reports available for remedial work and next service due



mbar

EST. 2001—NATIONWIDE

VACUUM PUMP & BLOWER OVERHAUL SPECIALISTS

ANY WHERE
ANY TIME
ANY BRAND



www.mbar.co.nz

24 hr phone 07 871 8192